



U.S. Department  
of Transportation  
Federal Aviation  
Administration

Central Region  
2300 East Devon Avenue  
Des Plaines, Illinois 60018

August 21, 1985

E-Z Heat Inc.  
ATTN: Mr. Todd A. Kirkman  
Route 1, Box 54  
Hillsdale, WI 54744

Gentlemen:

This is in response to your August 7, 1985 letter requesting clarification on how compliance can be recorded on your engine preheater installation.

Your device does not function during flight, so the only consideration with respect to safety of flight is that it neither interferes with functional equipment nor comes loose or detached and creates some other flight hazard. This equipment is installed on a nonfunctional, no-hazard basis and, as such, requires no approval on Supplemental Type Certificate. A further Federal Aviation Administration (FAA) review indicates it is not a major alteration of the airframe or engine. As such, it should be installed by an FAA licensed mechanic and made a matter of record by logbook entry. A Form 337 is not required.

If further clarification is required, please call Mr. Doral Miner at this office, phone (312) 694-7031.

Sincerely,

W. F. Horn  
Manager, Chicago Aircraft  
Certification Office, ACE-115C

